

General Specifications

Wrist bracelet operational temperature range:

- while charging: 0 – 45 °C
- while discharging: -20 – 60 °C

Wrist Bracelet Ingress Protection: IP67 - Dust Tight, Waterproof

Wrist Bracelet battery duration (when charged to full):

- storage mode: approx. 12 weeks
- operating without alarms: approx. 28h
- operating with alarm every 5 min: approx. 24h

Wrist Bracelet battery charging:

- approx. 3 hours from empty to full
- recommended to do full charge before entering the construction site or placed in storage mode

UPI charger operational temperature range: 0 – 45 °C

USB Support:

- Power Supply Input: 5V DC
- Connector type: micro-B form factor

UPI Charger Maximum Power Consumption:

- while charging: 1W
- stand-by mode: 0.27W

